WMP-Enforcement

27.085 SKF AUTOMOTIVE

JOHN ASHCROFT Governor

G. TRACY MEHAN III Director



STATE OF MISSOURI

DIVISION OF ENVIRONMENTAL QUALITY

DEPARTMENT OF NATURAL RESOURCES

Division of Energy Division of Environmental Quality Division of Geology and Land Survey Division of Management Services Division of Parks, Recreation, and Historic Preservation

ST. LOUIS REGIONAL OFFICE May 14, 1991

10805 Sunset Office Drive, Suite 100 St. Louis, MO 63127-1017 314-822-0101

Mr. C. William McGlocklin Fax No. 314-822-0943 Corporate Environmental Manager SKF USA. Inc. 1100 First Avenue King of Prussia, PA 19406-1352

L.O.W. #91-SL.024

Dear Mr. McGlocklin:

Enclosed, please find a report of a hazardous waste management inspection conducted at SKF Automotive Products by Mr. Bob Carlson of my staff on April 23, 1991.

Please note that the section titled "UNSATISFACTORY FEATURES" lists violations noted during the inspection, and the "RECOMMENDATIONS" section outlines steps the inspector has determined will correct those violations.

In order to document that corrective actions have been taken, you are requested to submit a written response no later than June 21, 1991. The response should describe the steps taken to correct each of the unsatisfactory features identified. Please direct the response to Mr. Carlson. You should also forward a copy of your response and supporting documentation to Mr. Bruce Martin, Chief - Hazardous Waste Enforcement, Waste Management Program, . P. O. Box 176, Jefferson City, MO 65102.

It is our purpose by this letter to persuade you to take all necessary actions to comply with the Missouri Hazardous Waste Management Law. Failure to achieve timely resolution of violations may result in the referral of this case for enforcement action by the Waste Management Program.

Should you have any questions, or wish to confer in this matter, please contact Mr. Carlson.

Sincerely,

ST. LOUIS REGIONAL OFFICE

Regional Administrator

RSPE/BC:ps

Enclosure

cc: Waste Management Program - Enforcement Mr. Don Kerns, WMP - Permits

MAY 17 1991

WASTE MANAGEMENT PROGRAM MISSOUR! DEPARTMENT OF NATURAL RESOURCES



Printed on recycled paper.

RESOURCE CONSERVATION AND RECOVERY ACT AND MISSOURI HAZARDOUS WASTE MANAGEMENT LAW COMPLIANCE EVALUATION INSPECTION REPORT

<u>Facility</u>

SKF Automotive Products 2320 Marconi Avenue St. Louis, MO 63110 EPA ID #: MOT300010345 MO Generator ID: 01115

<u>Participants</u>

Department of Natural Resources (MDNR)

Mr. Bob Carlson Environmental Specialist St. Louis Regional Office

Introduction

An inspection of SKF Automotive Products, located at the above address, was conducted on April 23, 1991. The inspection was conducted under the authority of the Resource Conservation and Recovery Act (RCRA) of 1976 and Sections 260.375(9) and 260.377 of the Missouri Hazardous Waste Management Law (1977) as amended. The inspection was confined to facets of the operation relevant to hazardous waste management.

Facility Description

The Marconi Avenue SKF facility has been closed since July, 1986, and the property was sold soon afterward. The current occupants of the different buildings have not changed since Mr. Kerwin Singleton's report of March 17, 1989. Building # 1 is still vacant, and possibly Building # 3 also, as no waste materials could be viewed through the windows.

The facility repeatedly requested a reclassification from interim status to generator only, in letters sent over several years. This was achieved for the SKF Foundry in Washington, Missouri, but not for the St. Louis facility. Various company representatives certified in letters to EPA Region VII and the MDNR Waste Management Program (WMP) that the facility had not used its interim status. However, Mr. Gaurang Shah's inspection report of September 10, 1984, indicated that hazardous waste had been stored for over 90 days, which would constitute use of interim status. This information was attributed to statements made by facility representatives during the inspection.

Until a decision is made by the WMP whether or not to cancel the facility's interim status, the requirements under 40 CFR 265 as incorporated in 10 CSR 25-7.265 still apply.

HANDOUS WASTE TREATMENT/STORAGE/DISSAL FACILITY Interim Status Checklist

Name of Facility: SKF Automotive Products Date: 4-23-91

Off-Site Facility?yn I.S. for	r:
Address: 2320 Marconi Hvenue	
st. Louis, MO 63110	RR TRANS LDR OTHER
Phone:()	115 EPA ID# MOT 3000 10 3 45
Facility Representative: N/A	Title: N/A
Briefly describe manufacturing process(es).(Use continuation sheet, if needed.)
facility has been closed si	nce 1986, but issues of
proper closure + financial as	ssurance documentation.
At issue is whether SKF eve	er actually made use of its
interim status by storing he	azardous waste over 90 days.
	é 12-13-88 inspection were noted.
	Ereport dated 3-17-89
List of wastes generated.(Use continuat: <u>Waste</u> <u>Amount</u>	t/Month Disposition
1N/A	DECE
	PECEIVE]
2.	MAY 17 1991
3	
4.	WASTE MANAGEMENT PROGRAM MISSOURI DE ARTIMENT OF
5	MATURAL RESOURCES
N/A	N/A
MANIFESTS AND RECORDREEPING 10 CSR 25-5.Z62(2) AND 5.262(2)(8) AND (D) 8. Generator's MO and EPA I.D. Numbers	PRETRANSPORT, CONTAINERIZATION AND LABELING 10 CSR 25-5.262(2) AND 5.262(2)(C)1
Manifest document number (MO I.D. & Shippent #)	Waste Packaged, marked and labeled per DOT during entire on-site storage period and prior to transport
EPA Waste I.D. codes	Placards available for use by transporters
Generator's name, address, phone #	Satellite accumulation requirements met (if applicable)
Proper DOT Shipping Name, Hazard Class and I.D. #	N/A
Containers. Quantity and Unit Wt/Vol being shipped properly designated .() C. Proper certification including waste minimization ()	WASTE ANALYSIS 10 CSR 25-7.265(2) AND 7.264(2)(8) Waste analysis plan
Manifest properly signed and dated	Identify hazardous wastes handled at facility.
No more than 10 days time between generator and facility signatures()	Means to confirm wastes received from off-site
Manifests returned within 35 days	SECURITY 10 CSR 25-7.265(1) AND 7.265(2)(3)
If not, exception generator report submitted within 45 days () Completed manifests and Summary Manifest Report and Certification, ()	24-hour surveillance system at facility or An artificial or natural boundary/controlled access
Spills of reportable quantities reported to DNR	Restricted access sign posted at each entrance
	Legible from a distance of 25 feet

Briefly describe waste streams managed at each TSD process.

	Waste	Amount/mon	th	Process	Design Capacity
	N/A				
	N/F				
,					
,	NIA			. / /14	
GENERAL INSPEC	TION 10 CSR 25-7.265(2) AND 7.265(2)(B)	J.	MANIFEST, I	RECORDS, REPORTING 10 Co	SR 25-7.265(2) AND 7.265(2)(E)
Facility inspe	cted and maintained				
inspection log	and written schedule for inspecting				
inspect emerge	ncy equipment				
Inspect securi	ty devices				
Inspect operat	ing and structural equipment		rating reco		
PERSONNEL TRAI	NING 10 CSR 25-7.265(2) AND 7.265(2)(8)		Descriptio	n, quantity, and TSD pr	ocess for all hazardous wastes ()
Documentation	of hazardous waste director's qualification:	or training ()	Location a	nd quantity of all hasa	rdous waste
Completed clas	sroom or on-the-job training	()	Waste anal	ysis records from off-s	nice sources
Job title, des	cription, and name of person filling position	on ()	-		ency incidents
britten record	of the type and amount of training given.	()			
Documentation	confirming that training has been given		Monitoring	, testing and analytica	al results if necessary ()
FREPAREDNESS A	NO PREVENTION 10 CSR 25-7.265(2) AND 7.265()	Rep 2)(C)	porting		
	nication or alarm system				ff-site facilities
	hazardous vaste operation area capable of s		•		closure
• .	stance				1 25-7.265(2) AND 7.265(2)(1) N/A
	spill control, and decontamination equipment			s closed and in good co	endition
	supply for fire control equipment roper safety equipment available				
•	Space		Hazardous	waste containers store	age area inspected once a week
·	ith local emergency agencies		Inspectio	n log	
_	AN AND EMERGENCY PROCEDURES 10 CSR 25-7.263			s holding ignitable or line	reactive waste at least 50 ft. from the
Contingency pl	an	()	Incompati	ble waste placed in di	fferent containers
Detailed descr	iption of procedures that personnel must im	plement in			hazardous waste which are incompatible with lkes, berms, walls, or other devices()
	res, explosions, or release of hazardous wa				sinment system (if applicable) meeting
Names, address	l arrangements with emergency agencies es and phone numbers (home & office) of eme	rgency	criteria	of 10 CSR 25-7.265(2)(1	D
	pment including its description and location	L.	(See Tank	Checklist)	5-7.265(2) AND 7.265(2)(J) N/A
Evacuation plan	n if applicable	() H.	. INTERIN S	TATUS SURFACE IMPOUNDED	DVTS 10 CSR 25-7.265(2) AND 7.265(2)(K)
LASTE CIL 10 C	SR 25-11.010 N/A				poundment
Waste oil prop	erly handled	· · · · · · · · · · · · · · · · · · ·	Earthen d	ikes have protective co	overs
britten waste	oil contract maintained				expansions of existing surface uble liner and leachate system
			placing a	substantially differen	tten documentation obtained before nt hazardous waste into a surface treatment
			Freeboard	level inspected each	operating day
			Dikes & v	egetation inspected we	ekly for lacks, deterioration or failurest
			Inspection	ns recorded in inspect	ion logs
					d so that mixture no longer meets the tive
			Incoment	ble wester secretared	in separate surface impoundments ()

, N.	GROUNDWATER MONITORING 10 CSR 25-7.265(2) A Applicable to surface impoundments, landfil	ND 7.265(2)(F) ND 1.265(2)(F)	1/A				
	Groundwater monitoring wells installed		()				
	Wells are structurally sound		()				
	Sampling and analysis plan on-site		()				
	Samples and groundwater levels taken		()				
	Groundwater monitoring results kept		()				
0.	CLOSURE AND POST-CLOSURE 10 CSR 25-7.265(2)	AND 7.265(2)(G)					
	Closure plan for facility		()				
Description of how and when facility will be closed							
	Estimate of maximum inventory of hazardous	waste					
•	Steps to decontaminate equipment		()				
	Post-closure plan for disposal fácilities o	mly					
P.	FINANCIAL REQUIREMENTS 10 CSR 25-7.265(2) A	ND 7.265(2)(H)					
	Cost estimate for facility closure		()				
	Financial assurance for closure and post-cl	osure	()				
	Liability for sudden accidents		()				
	Liability for non-sudden accidents for disp	oosal only					
COMMENTS: red	serred to Don Ken	S, WMP	sernit section,				
for review	<i>1</i> .		•				
	•						
-			······································				
Inspector Signat	ure & Title: M	- L	ESIL				
	Office: SLR	<u>'-0</u>					
			IN COMPLIANCE (4			

IN VIOLATION OR ABSENT

(-)